Reduction & Analysis of PDV data from Ring expansion test

October 23rd, 2012

Shweta Gupta[1]

Jason Johnson[2] & Glenn S. Daehn[2]

[1]Dept. of Mechanical Engineering,
[2]Dept. of Material Science & Engineering

Outline

- Motivation
- Methods
- Results
- Discussion
- Conclusion

Motivation

- Develop MATLAB code for automated analysis of ring expansion PDV data for the determination materials constitutive properties

- Design and deployment of stand alone test systems for high strain rate materials behavior

- Wave free uniform tension test method to compare/supplant split Hopkinson pressure bar technique

Method

Free Body Diagram

Ring sample

Ring segment

$$\Lambda = bhrd\theta$$

$$\rho\Lambda\frac{d^2r}{dt^2} = P(t)\frac{\Lambda}{b} - \sigma_h(t)\frac{\Lambda}{r} \quad \longrightarrow \quad \text{For P(t)} \approx 0 \quad \longrightarrow \quad \boxed{\sigma_h(t) = -r\rho\frac{d^2r}{dt^2}}$$

Experimental Setup

Vaporizing wire technique

Electromagnetic ring expansion

Picture courtesy: Constitutive relation development through the FIRE test
J. R. Johnson, G. A. Taber, and G. S. Daehn

Elastomer

Ring sample

Wire

Electrical current

Axial force

Optional steel "catchers"

Driver ring

Solenoid

Electrical current

DEPARTMENT OF
MATERIALS SCIENCE
AND ENGINEERING

THE OHIO STATE UNIVERSITY

Flowchart for data reduction

Get basic inputs of the geometry and experiment → Raw Data → Spectrogram •Select the working window → Select Frequency of the signal

↓

Get velocity from the frequency ← Fit the velocity to get its derivative and integral ← Get the stress and strain for free expansion of the ring ← We have the stress strain curve

Results

Annealed Cu 101 rings

- 50.5mm I.D. x 53.34mm O.D. x 10mm rings

- Exploding wire actuator, 0.8mm wire

- Launched with 8kJ, 12kJ and 16kJ energy

16kJ

12kJ

8kJ

Test specimen

Raw data to spectrogram

# Frequency, Velocity & Displacement

# Fit velocity with quadratic fit

8kJ Cu 101

12kJ Cu 101

16kJ Cu 101

Discussion

Comparison of different fits

- Velocity plots

Velocity plot at 8kJ

Velocity plot at 12kJ

- Stress plots

Stress plot at 8kJ

Stress plot at 12kJ

# Comparing stress and strain rates for all three shots

Scope of improvement

- Problem with Fourier fit

Missing data

Conclusions

- Moving towards automatic extraction of velocity and stress-strain data from the PDV signal with minimum user intervention.

- Obtaining high-fidelity data from the PDV is important.

- Three tests with 8kJ, 12kJ and 16kJ were performed on annealed Cu101 in which maximum strain rate of about 5000 s^{-1} with a total strain about 40% was achieved .

- Very subtle variations fitting function forms, all of which fit well, give significant variations in the apparent stress-strain curve.

Questions??